

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: April 16, 2009 **Name:** Steven Langseder
Weather
Conditions: Sunny, 50°F

General Inspection:

	(Y/N)
Is the Milnor Street entrance secure?	<u>Yes</u>
Is the Cottman Ave entrance secure?	<u>Yes</u>
Are there any breaches in site security in the site gate/fence?	<u>Yes</u>
If Yes, describe in detail below and mark on the attached site map.	
<u>The fence along Milnor Street was damaged by the wind (i.e. blown over). The</u>	
<u>green privacy fence was torn from several locations along Cottman Avenue.</u>	
<u>The chainlink and privacy fences were repaired on Thursday, April 16th.</u>	
Site sign remains in good condition?	<u>Yes</u>
If no, please explain:	
<u></u>	
<u></u>	
Are the circuit breakers locked and secured?	<u>Yes</u>

Building 7:

Are the doors to Building 7 locked?	<u>Yes</u>
Has security for Building 7 been breached?	<u>No</u>
Is the high visibility fence and welded wire still in place at the front door?	<u>Yes</u>
Comments:	
<u></u>	
<u></u>	
<u></u>	

Exclusion Zone:

Zone remains well defined (i.e., construction fence remains intact)?	<u>Yes/No</u>
Sheet Pile Wall remains in good condition?	<u>Yes</u>
Marine Mattresses remain covered?	<u>No</u>
If no, please specify areas that need to be addressed:	
<u>The Exclusion Zone remains defined; however, sections of the high visibility orange</u>	
<u>fence are damaged and will have to be replaced during the re-mobilization to the</u>	
<u>Site.</u>	
Are the fish warning signs still hanging?	<u>Yes</u>

Additional Notes or Comments:

Several marine mattress stockpiles were partially uncovered due to the wind. TtEC will

contact MidLantic to arrange to have the covers repaired.

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: April 16, 2009 **Name:** Steven Langseder

Weather

Conditions: Sunny, 50°F

E&S Measures

Are there any breaches or damage to the silt fence in the Courtyard Area?	(Y/N)
If yes, please describe in detail and mark on attached site map:	<u>No</u>

Are repairs necessary?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Are there any breaches in the Support Area?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Are repairs necessary?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Additional Notes or Comments:

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: April 16, 2009 **Name:** Steven Langseder

Weather

Conditions: Sunny, 50°F

E&S Measures

Are there any breaches in the Exclusion Zone? (Y/N)
No

If yes, please describe in detail and mark on attached site map:

The silt fence near the eastern return of the sheetpile wall was damaged and the
support post on the end of the fence was leaning. The fence post was hammered
into the ground, a new post was installed to support the silt fence, and stones and
concrete rubble were placed at the base of the silt fence to prevent erosion

Are repairs necessary? Yes

If yes, please describe in detail and mark on attached site map:

Are there any breaches in the Sheet Pile Wall Area? No

If yes, please describe in detail and mark on attached site map:

Are repairs necessary? No

If yes, please describe in detail and mark on attached site map:

Additional Notes or Comments:

Date: April 16, 2009 **Name:** Steven Langseder
Weather
Conditions: Sunny, 50°F

Bill Burke of TtEC and Steven Langseder of Malcolm Pirnie, Inc. performed the weekly site inspection on Thursday, April 16, 2009.